


K₂SO₄ production from Na₂SO₄



Reaction equations



Main Process Steps: Two — Step — Conversion (t = 25 °C)

Thenardite + Sylvite Glaserite SOP

Process flow sheet



CONTACT: